## AN INNOVATIVE GSFC METHODOLOGY FOR USING FMECA AS A RISK ASSESSMENT AND COMMUNICATION TOOL

Nancy J Lindsey Sr. Reliability Manager , Code 371 NASA GSFC

RAMS 2016 FMEA SESSION - 01D Jan 25, 2016 10:15 AM

# AGENDA

Introduction to Risk Management & FMECA
 FMECA Risk Assessment Methodology
 Examples
 Conclusions & Recommendations



### FAILURE MODE EFFECTS AND CRITICALITY ANALYSIS (FMECA)

- Failure Mode Effects and Criticality Analysis is a bottoms-up inductive analysis
  of potential failures. That is performed at the functional, interface, and/or
  detailed level on a system or process.
- The purpose of any FMECA is to:
  - Postulate where there is the potential for irreversible physical and/or functional damage/failure;
  - + Identify how damage/failures propagate or not;

- + Identify how damage/failures impacts system
- + Identify the means available for failure detection, isolation, and/or mitigation;
- + Recommend/Track corrective actions and their implementation/effectiveness.



NASA/GSFC uses FMECAs to continually identify plausible system failures and causes and analyze their implications and mitigations.

# **RISK MANAGEMENT & FMECA**

- NASA/GSFC employs Continuous Risk Management (CRM)/Risk Informed Decision Making (RIDM) to make decisions on design, manufacturing, and operations of on-orbit assets based on the risk to achieving mission success
- NASA/GSFC uses FMECAs to continually identify plausible system failures and causes and analyze their implications and mitigations or mission failure risks.

How the FMECA process fits in:



Both Risk Management and FMECAs are living processes at GSFC throughout a mission's life.

## FMECA RISK ASSESSMENT METHODOLOGY

- 1. Correlating Mission Specific Success Requirements-to-GSFC Risk Management Consequence Definitions (GPR 7120.4D);
- Correlating Failure Severities (NASA/GSFC Failure Mode Effect and Criticality Analysis Procedures)-to-GSFC Risk Management Consequence Definitions (GPR 7120.4D);
- 3. Correlating Mission Failure and Duration-to-GSFC Risk Management Likelihood Definitions (GPR 7120.4D);
- 4. Analyzing and characterizing each failure mode using these correlations;
- 5. Assessing the Failure Modes/Critical Items/Single Point Failures as risks and documenting and communicating risks to mission risk managers.



## CORRELATING MISSION SUCCESS -TO-GSFC RISK MANAGEMENT CONSEQUENCE DEFINITIONS

- NASA/GSFC has a center standard consequence risk scale.
- Each GSFC project or mission has unique mission success requirements
- Correlation of these two criteria allows each Failure Mode to have a risk based consequence rating.

	Consequence Categories							
Risk	1 Very Low	2 Low	3 Moderate	4 High	5 Very High			
Safety Negligible or No impact. Could cause the need for only minor first aid inless or r property d		May cause minor injury or occupational illness or minor property damage.	May cause severe injury or occupational illness or major property damage.	May cause death or permanently disabling injury or destruction of property.				
Technical	No impact to full mission success criteria	Minor impact to full mission success criteria	Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin	Major impact to full mission success criteria. Minimum mission success criteria is achievable	Minimum mission success criteria is not achievable			
Schedule	Negligible or no schedule impact	Minor impact to schedule milestones; accommodates within reserves; no impact to critical path	Impact to schedule milestonee; accommodates within impact to rifical path or rifical path		Cannot meet schedule and program milestones			
Cost	<2% increase over allocated and negligible impact on reserve	Between 2% and 5% increase over allocated and can handle with reserve	Between 5% and 7% increase over allocated and can not handle with reserve	Between 7% and 10% increase over allocated, and/or exceeds proper reserves	>10% increase over allocated, and/or can't handle with reserves			

1 Very Low       No impact to full mission success criteria → Threshold and Baseline Science can still be achieved         2 Low       Minor impact to full mission success criteria → Threshold Science can still be achieved; Baseline Science may be degraded or performed at a reduced level         3 Moderate       Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin →         4 High       All of the Threshold Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)         4 High       Major impact to full mission success criteria. Science performance requirements         5 Very High       Minimum mission success criteria is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance requirements		Technical Consequence
2 Low       Minor impact to full mission success criteria → Threshold Science can still be achieved; Baseline Science may be degraded or performed at a reduced level         3 Moderate       Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin →         3 Moderate       All of the Threshold Science is still achievable; Not all Baseline Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)         4 High       Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements         5 Very High       Minimum mission success criteria is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)	1 Very Low	No impact to full mission success criteria → Threshold and Baseline Science can still be achieved
<ul> <li>Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin →</li> <li>All of the Threshold Science is still achievable; Not all Baseline Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)</li> <li>Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements</li> <li>Very High</li> <li>Very High</li> </ul>	2 Low	Minor impact to full mission success criteria → Threshold Science can still be achieved; Baseline Science may be degraded or performed at a reduced level
<ul> <li>4 High</li> <li>Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements</li> <li>5 Very High</li> <li>Minimum mission success criteria is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)</li> </ul>	3 Moderate	Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin → All of the Threshold Science is still achievable; Not all Baseline Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)
5 Very High Minimum mission success criteria is not achievable → Threshold and Baseline Science is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)	4 High	Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements
	5 Very High	Minimum mission success criteria is not achievable → Threshold and Baseline Science is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)

## CORRELATE FAILURE SEVERITIES-TO-GSFC RISK MANAGEMENT CONSEQUENCE DEFINITIONS

- NASA/GSFC also has a center tailorable standard safety based FMECA severity scale.
- With the development of the risk based consequence rating scale
- Correlation of the FMECA/Safety categories and the risk based consequence scale allows for safety and risk failure mode characterization.

Category	Severity	Description
1	Catastrophic	Failure modes that could result in serious injury, loss of life (flight or ground personnel), or total loss of mission.
1R		Failure modes of identical or equivalent redundant hardware items that, if all failed, could result in Category 1 effects.
1S		Failure in a safety or hazard monitoring system that could cause the system to fail to detect a hazardous condition or fail to operate during such condition and lead to Category 1 consequences.
2	Critical	Failure modes that could result in loss of one or more minimum mission objectives as defined by the GSFC project office.
2R		Failure modes of identical or equivalent redundant hardware items that could result in Category 2 effects if all failed.
3	Significant	Failure modes that could cause degradation to full mission objectives and still meet a minimum mission.
4	Minor	Failure modes that could result in insignificant or no loss to mission objectives

	Technical Consequence	Failure Severity			
T very Low	No impact to full mission success criteria → Threshold and Baseline Science can still be achieved	Minor or no impact on mission life or performance: noticeable or no degradation, that does not lead to loss of science or significant peril to mission. (Category 4)			
2 Low	Minor impact to full mission success criteria → Threshold Science can still be achieved; Baseline Science may be degraded or performed at a reduced level	Potential for major or significant degradation of mission or performance: no immediate impact on mission, but potential exists for future loss, at level 5-3, if adequate alternatives or measures are not implemented. (Category 3)			
3 Moderate	Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin → All of the Threshold Science is still achievable; Not all Baseline Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)	Significant loss or degradation of mission: significant loss of mission function leading to a significant loss of data, or a significant reduction in life of the mission. (Category 2 or 3) Or Loss or degradation of a redundant subsystem or science instrument producing levels 4 or 3 severity, if remaining redundancy is lost. (Category 2R)			
4 High	Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements	Major loss or degradation of mission: capability to complete some mission objectives (Category 2) Or Loss or degradation of a redundant subsystem producing levels 4 or 5 severity, if remaining redundancy is lost. (Category 1R)			
5 Very High	Minimum mission success criteria is not achievable → Threshold and Baseline Science is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)	Complete loss of mission: complete loss of primary mission capability. (Category 1) Or Loss or degradation of a subsystem or science leading to safety or hazard monitoring system failure that could cause the system to fail to detect a hazardous condition or fail to operate during such condition and lead to Severity 5 consequences (Category 1S)			

## CORRELATE MISSION FAILURE AND DURATION-TO-GSFC LIKELIHOOD DEFINITIONS

- NASA/GSFC has a center standard likelihood risk scale
- Each GSFC project or mission has unique mission success duration requirement
- Correlation of these two criteria allows each Failure Mode to have a risk based likelihood rating.

Likelihood	Safety (Estimated likelihood of safety event occurrence)	Technical (Estimated likelihood of not meeting performance requirements)	Cost/Schedule (Estimated likelihood of not meeting cost or schedule commitment)
5 Very High	(P <sub>SE</sub> > 10 <sup>-1</sup> )	(P <sub>T</sub> > 50%)	(P <sub>CS</sub> > 75%)
4 High	(10 <sup>-2</sup> < P <sub>SE</sub> ≤ 10 <sup>-1</sup> )	(25% < P <sub>T</sub> ≤ 50%)	(50% < P <sub>CS</sub> ≤ 75%)
3 Moderate	(10 <sup>-3</sup> < P <sub>SE</sub> ≤ 10 <sup>-2</sup> )	(15% < P <sub>T</sub> ≤ 25%)	(25% < P <sub>CS</sub> ≤ 50%)
2 Low	(10 <sup>-5</sup> < P <sub>SE</sub> ≤ 10 <sup>-3</sup> )	(2% < P <sub>T</sub> ≤ 15%)	(10% < P <sub>CS</sub> ≤ 25%)
1 Very Low	(10 <sup>-6</sup> < P <sub>SE</sub> ≤ 10 <sup>-5</sup> )	(0.1% <p<sub>T≤ 2%)</p<sub>	(2% < P <sub>CS</sub> ≤ 10%)

 $\lambda = \frac{\ln(1-P_f)}{-time} = \frac{\ln(1-P_f)}{-27720 \, hrs}$ 

/alue	Occurrence or Likelihood
5	Very High (0.50 < $P_F$ ) Or (2.5 x10 <sup>-5</sup> < $\lambda$ for mission duration)
4	High (0.25 < $P_F \le 0.50$ ) Or (1.03 x10 <sup>-5</sup> < $\lambda$ ≤ 2.5 x10 <sup>-5</sup> for mission duration)
3	Moderate (0.15 < $P_{\rm F} \le$ 0.25) Or (5.9 x10^6 < $\lambda \le$ 1.03 x10^5 for mission duration)
2	Low (0.02 < $P_{\rm F}$ $\leq$ 0.15) Or (7.3 x10 $^7$ $\lambda \leq$ 5.9 x10 $^6$ for mission duration)
1	Very Low (0.001 <p_f <math="" display="inline">\leq 0.02) Or (3.6 x10^8 &lt; <math display="inline">\lambda</math> &lt; 7.3 x10^7 for mission duration)</p_f>
< 1	Very Very Low ( $P_F \le 0.001$ ) Or ( $\lambda < 3.6 \times 10^{-8}$ for mission duration)

### ANALYZE AND CHARACTERIZE EACH FAILURE MODE

- 1. Postulate all potential failure modes
- 2. Identify causes and impacts of each failure mode
- Ascertain each failure mode's or cause's available prevention and/or mitigation strategies and detection capabilities
- Using the correlations as shown characterize each failure modes by assigning a occurrence, consequence, and detection/prevention value.

	Likelihood	Technical Consequence	Failure Severity	Detection/Prevention
<1 Very Very Low	Very Very Low ( $P_{\rm F} \le 0.001$ ) Or ( $\lambda < 3.6 \times 10^8$ for mission duration)		N/A	
1 Very Low	Very Low (0.001 <p<sub>F <math>\leq</math> 0.02) Or (3.6 x10<sup>8</sup> &lt;<math>\lambda</math>&lt; 7.3 x10<sup>-7</sup> for mission duration)</p<sub>	No impact to full mission success criteria → Threshold and Baseline Science can still be achieved	Minor or no impact on mission life or performance: noticeable or no degradation, that does not lead to loss of science or significant peril to mission. (Category 4)	Certain - failure will be detected and prevented or mitigated
2 Low	Low (0.02 < $P_F \le 0.15$ ) Or (7.3 x10 <sup>7</sup> < $\lambda \le 5.9 x10^8$ for mission duration)	Minor impact to full mission success criteria → Threshold Science can still be achieved; Baseline Science may be degraded or performed at a reduced level	Potential for major or significant degradation of mission or performance: no immediate impact on mission, but potential exists for future loss, at level 5-3, if adequate alternatives or measures are not implemented. (Category 3)	Moderate to High - Failure is likely to be detected before occurrence and has a good chance of being prevented or mitigated
3 Moderate	Moderate (0.15 < $P_F ≤ 0.25$ ) Or (5.9 x10 <sup>-6</sup> <λ≤ 1.03 x10 <sup>-5</sup> for mission duration)	Moderate impact to full mission success criteria. Minimum mission success criteria is achievable with margin — All of the Threshold Science is still achievable; Not all Baseline Science is achievable (e.g., Cannot perform science at one or more Baseline Science performance levels)	Significant loss or degradation of mission: significant loss of mission function leading to a significant loss of data, or a significant reduction in life of the mission. (Category 2 or 3) Or Loss or degradation of a redundant subsystem or science instrument producing levels 4 or 3 severity, if remaining redundancy is lost. (Category 2R)	Low to Moderate - Failure may be detected and may be prevented or mitigated
4 High	High (0.25 < $P_{F}$ ≤ 0.50) Or (1.03 x10 <sup>5</sup> < $\lambda$ ≤ 2.5 x10 <sup>5</sup> for mission duration)	Major impact to full mission success criteria. Minimum mission success criteria is achievable → Threshold Science is still achievable; Cannot meet any Baseline Science performance requirements	Major loss or degradation of mission: capability to complete some mission objectives (Category 2) Or Loss or degradation of a redundant subsystem producing levels 4 or 5 severity, if remaining redundancy is lost. (Category 1R)	Remote - Unlikely failure will be detected or prevented or mitigated
5 Very High	Very High (0.50 < P <sub>F</sub> ) Or (2.5 x10 <sup>5</sup> <\.for mission duration)	Minimum mission success criteria is not achievable → Threshold and Baseline Science is not achievable. (e.g., Cannot perform science at one or more Threshold Science performance levels)	Complete loss of mission: complete loss of primary mission capability. (Category 1) Or Loss or degradation of a subsystem or science leading to safety or hazard monitoring system failure that could cause the system to fail to detect a hazardous condition or fail to operate during such condition and lead to Severity 5 consequences (Category 19)	None - Failure will not be detected and will not be prevented or mitigated

## FAILURE MODE EXAMPLE



Goddard Space Flight Center

NASA

## **Assess and Communicate Risks**

- Use the FMECA Matrices to Summarize Risks for Assessment and Communication
- Assess and Prioritize the risk of each characterized Failure Mode
  - Formulate Critical Items List
  - Formulate Single Point Failure List
- Develop and Propose Risk Statements



Note: Matrices do not take the place of Risk Statement proposals but rather they support and justify proposals

## EXAMPLE: (L x C)

LEO Science Mission



## EXAMPLE (RPN x C)

### ISS Mission Example

	Very High	26- 125							Detection
	High	21-25							in
	Moderate	16-20					4.4-1, 4.7-1 (2)		unavailable but mission
	Low	11-15	4.1-10 (1)	4.1-2, 4.1-12 (2)					is not lost
	Very Low	6-10							CSEC Cradible Bick Thrashold
Risk Priority Number (RPN)	Very Very Low	1-5	2.34+1, 2.35+1, 2.73+1, 2.73+2, 2.74+1, 2.74+2, 2.75+2, 4.1+4, 4.2+1, 4.3+1, 4.1+5, 4.1+6, 4.1+ 7, 4.1+8 (14)	$\begin{array}{l} 1.1-1,  1.1-2,  1.2-2,  1.3-1,  1.3-2, \\ 1.4-2,  1.5-1,  1.5-2,  1.8-1,  1.8-2, \\ 2.1-2,  2.2-2,  2.5-2,  2.6-2,  2.9-1, \\ 2.14-1,  2.15-1,  2.17-1,  2.23-1, \\ 2.25-1,  2.26-1,  2.27-1,  2.28-1, \\ 2.29-1,  2.30-1,  2.31-1,  2.32-1, \\ 2.33-1,  2.48-1,  2.50-1,  2.51-1, \\ 2.52-11,  2.53-1,  2.54-1,  2.55-1, \\ 2.55-118,  2.56-1,  2.56-1,  2.57-1, \\ 2.56-11,  2.65-1,  2.66-1,  2.67-1, \\ 2.64+1,  2.65-1,  2.66-1,  2.67-1, \\ 2.68-1,  2.69-1,  2.70-1,  2.70-2, \\ 2.70-3,  2.70-4,  2.71-1,  2.72-1, \\ 4.1-15,  4.1-16,  4.1-17 \\ (54) \end{array}$	2.10-1, 2.11-1, 2.43-1, 2.45-1, 2.61-1, 2.61-2, 2.61-3, 2.61-4, 2.62-1, 2.75-1, 3.1-2 (11)	$\begin{array}{c} 1.6-1, 1.6-2, 1.7-\\ 1, 1.7-2, 2.1-1,\\ 2.2-1, 2.5-1, 2.5-\\ 3, 2.6-1, 2.7-1,\\ 2.8-1, 2.10-1,\\ 2.12-1, 2.13-1,\\ 2.12-1, 2.13-1,\\ 2.20-1, 2.22-1,\\ 2.24-1, 2.37-1,\\ 2.38-1, 2.39-1,\\ 2.41-1, 2.42-1,\\ 2.44-1, 2.46-1,\\ 2.44-1, 2.46-1,\\ 2.47-1, 2.76-1,\\ 2.76-2, 2.77-1,\\ 2.78-1, 2.79-1\\ (32)\end{array}$	3.1·1, 3.1·2, (2)	$\begin{array}{c} 1.2-1, 1.4-1, \\ 3.1-3, 3.1-4, \\ 4.1-1, 4.1-3, \\ 4.1-9, 4.1-11, \\ 4.1-9, 4.1-11, \\ 4.1-2, 4.4-2, 4.4-2, \\ 4.5-1, 4.6-1, 4.6-2, 4.7-2 \\ (16) \end{array}$	16 SPFs but all have Low Probability of Failure thus representing only a Very Very Low Risk.
FMEA Severity		4	3	2R	2	1R			
			1	2		3	4	5	
				Seve	rity				

# CONCLUSIONS

#### Methodology Benefits:

- Easily shows and begins action/risk management;
- Provides a quick communication mechanism of failure risks and FMECA results;
- Offers a direct translation of SPFs to risks;
- Is easily tailored for mission length and risk tolerance profile;
- Requires care in implementation by reliability personnel to account for and ensure consistency in the application of the one-to-many cases in the correlations of Technical Consequence to Failure Severity Categories;
- Makes the formulation of CIL and SPF lists and communication of safety issues more efficient and verifiable.

#### **Recommendations:**

- Define up-front risk definitions for consequence and likelihood;
- Establish and understand the mission/project/system success criteria and allowable degradations or mitigation strategies within the success criteria;
- Agree and implement risk management strategies and philosophies consistent with mission/project/system and or organizational risk tolerance intensities;
- Acquire up-front agreement on FMECA correlations especially criticality levels;
- Involve designers, safety, quality, management, and systems engineering in the failure postulation and analysis.

The GSFC FMECA Risk Assessment and Communication Methodology is valid for all spaceflight mission and industries.

# ACKNOWLEDGEMENTS

- ICESAT-2, OSIRIS-Rex, Robotic Refueling Mission (RRM), Gravity and Extreme Magnetism SMEX (GEMS), and Nuclear Spectroscopic Telescope Array (NuSTAR)Projects
- \* GSFC SMA Mission Assurance Directorate
- \* GSFC Risk and Reliability Branch (Code 371)
- \* Peers and Orson John, Aron Brall, & Syed Aziz
- Reliability and Maintainability Symposium (RAMS)